

Dangers caused by rotting of insect-damaged open-line wooden construction masts

Gronemann H.

Zentralblatt fur Arbeitsmedizin und Arbeitsschutz

1961; 11:153-157

ARTICLE IDENTIFIERS

DOI: unavailable

PMID: 13708908

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0044-4049

eISSN: not available

OCLC ID: 01770579

CONS ID: not available

US National Library of Medicine ID: 7610692

This article was identified from a query of the SafetyLit database.