

**Problems during infusions. Severe electrical shock occurred during use of Welmed P1000 syringe pump**

Ford P, Wood D.

British medical journal: BMJ

1995; 310(6989):1271

**ARTICLE IDENTIFIERS**

DOI: unavailable

PMID: 7767221

PMCID: PMC2549655

**JOURNAL IDENTIFIERS**

LCCN: not available

pISSN: 0959-8138

eISSN: 1468-5833

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.