

## **Rockfall hazard zones in Austria. Experience, problems and solutions in the development of a standardised procedure**

Mölk M, Rieder B.

Geomechanics and tunnelling

2017; 10(1):24-33

### **ARTICLE IDENTIFIERS**

DOI: 10.1002/geot.201600065

PMID: unavailable

PMCID: not available

### **JOURNAL IDENTIFIERS**

LCCN: not available

pISSN: 1865-7362

eISSN: 1865-7389

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.