

Analysis of an explosion accident at Dangyang Power Plant in Hubei, China: causes and lessons learned

Fu G, Zhou L, Wang J, Shi M.

Safety science

2018; 102:134-143

ARTICLE IDENTIFIERS

DOI: 10.1016/j.ssci.2017.10.010

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: 91640944

pISSN: 0925-7535

eISSN: 1879-1042

OCLC ID: 23966897

CONS ID: sn 91-38208

US National Library of Medicine ID: 9114980

This article was identified from a query of the SafetyLit database.