

Investigation of in-flight shutdown of turboprop engine due to electrical discharge damage

Lee B, Kim GH, Karkkainen RL, Hwang YH.

Journal of failure analysis and prevention

2018; 18(1):92-100

ARTICLE IDENTIFIERS

DOI: 10.1007/s11668-018-0384-x

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 1547-7029

eISSN: 1864-1245

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.