

## **Cracking of erosion strip of main rotor blade of a military helicopter**

Nandi V, Bhat RR, Prasad VR.

Journal of failure analysis and prevention

2019; 19(1):36-44

### **ARTICLE IDENTIFIERS**

DOI: 10.1007/s11668-019-00594-1

PMID: unavailable

PMCID: not available

### **JOURNAL IDENTIFIERS**

LCCN: not available

pISSN: 1547-7029

eISSN: 1864-1245

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.