

Failure of concrete-face sand-gravel dam due to water flow overtops

Journal of performance of constructed facilities
2019; 33(2):e04019007

ARTICLE IDENTIFIERS

DOI: 10.1061/(ASCE)CF.1943-5509.0001275
PMID: unavailable
PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available
pISSN: 0887-3828
eISSN: 1943-5509
OCLC ID: not available
CONS ID: not available
US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.