

The Causes of Building Accidents in the Hermann Goering Street in Berlin

Pucher A.

Zeitschrift des Vereines Deutscher Ingenieure

1937; 81:801-802

ARTICLE IDENTIFIERS

DOI: unavailable

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0341-7255

eISSN: not available

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.