

# **Modeling "wrong side" failures caused by geomagnetically induced currents in electrified railway signaling systems in the UK**

Patterson CJ, Wild JA, Boteler DH.

Space Weather

2023; 21(12):e2023SW003625

## **ARTICLE IDENTIFIERS**

DOI: 10.1029/2023SW003625

PMID: unavailable

PMCID: not available

## **JOURNAL IDENTIFIERS**

LCCN: 2002211771

pISSN: not available

eISSN: 1542-7390

OCLC ID: 51165186

CONS ID: not available

US National Library of Medicine ID: 101661963

This article was identified from a query of the SafetyLit database.