

# **Failure investigation of transmission line towers with unfilled bolt holes in stub member**

Balagopal R, Rao NP, Palani GS, Rokade RP.

J. Inst. Eng. India Ser. A

2023; 104(4):867-876

## **ARTICLE IDENTIFIERS**

DOI: 10.1007/s40030-023-00766-1

PMID: unavailable

PMCID: not available

## **JOURNAL IDENTIFIERS**

LCCN: not available

pISSN: 2250-2149

eISSN: 2250-2157

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.