

Study on causes of string hole in gas extraction cross seam under disturbance of hydraulic reaming

Wang J, Liu Q, Bao K.

China safety science journal (CSSJ)

2019; 29(11):164-170

ARTICLE IDENTIFIERS

DOI: 10.16265/j.cnki.issn1003-3033.2019.11.026

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 1003-3033

eISSN: not available

OCLC ID: 55656394

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.