

## **Foreseeable errors in the use of foot controls on industrial machines**

Trump TR, Etherton JR.

Applied ergonomics

1985; 16(2):103-111

### **ARTICLE IDENTIFIERS**

DOI: unavailable

PMID: 15676539

PMCID: not available

### **JOURNAL IDENTIFIERS**

LCCN: 71244723

pISSN: 0003-6870

eISSN: 1872-9126

OCLC ID: 01702062

CONS ID: not available

US National Library of Medicine ID: 0261412

This article was identified from a query of the SafetyLit database.