

A case of accidental electrocution. Identification of metallization on the electric marks with an energy dispersive X-ray microanalyzer

Tomita M, Ijiri I, Shimosato K, Mikami Y, Doi Y, Uehira K.

Nippon Hoigaku Zasshi

1984; 38(1):59-63

ARTICLE IDENTIFIERS

DOI: unavailable

PMID: 6471574

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: sn 84001030

pISSN: 0047-1887

eISSN: not available

OCLC ID: 10462928

CONS ID: not available

US National Library of Medicine ID: 0413715

This article was identified from a query of the SafetyLit database.