Ignition hazard from drilling into sealed frames of agricultural equipment

Applied occupational and environmental hygiene 2002; 17(2):82-83

ARTICLE IDENTIFIERS

DOI: 10.1080/104732202317201294

PMID: 11843201 PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available pISSN: 1047-322X eISSN: 1521-0898 OCLC ID: not available CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.