

Analysis of a safety device for high speed separators

Holm G.

Reliability engineering

1982; 3(1):73-83

ARTICLE IDENTIFIERS

DOI: 10.1016/0143-8174(82)90023-3

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0143-8174

eISSN: not available

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.