

Fire damage to aluminum wired receptacles. technical note

Beland B, Saucier D.

Fire technology

1986; 22(4):341-345

ARTICLE IDENTIFIERS

DOI: 10.1007/BF01038245

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: 65009890

pISSN: 0015-2684

eISSN: 1572-8099

OCLC ID: 1569307

CONS ID: FITCAA

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.