

## **Improper construction results in dangerous stairs: Large top runs produce fall hazard**

Johnson D, Johnson DA.

Proceedings of the Human Factors and Ergonomic Society annual meeting  
2009; 53(9):576-580

### **ARTICLE IDENTIFIERS**

DOI: 10.1177/154193120905300908

PMID: unavailable

PMCID: not available

### **JOURNAL IDENTIFIERS**

LCCN: not available

pISSN: 2169-5067

eISSN: 1541-9312

OCLC ID: 28563946

CONS ID: not available

US National Library of Medicine ID: 9420718

This article was identified from a query of the SafetyLit database.