

**Aluminum metal combustible dust explosion from improper design,
construction and use of dust collection system sends two employees by life
flight to burn centers**

Keown D.

Journal of occupational and environmental hygiene
2016; 13(9):D135-7

ARTICLE IDENTIFIERS

DOI: 10.1080/15459624.2016.1177643

PMID: 27074058

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 1545-9624

eISSN: 1545-9632

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.