

An investigation on the mechanisms of instabilities and safe design of the south slope at a lignite pit (SW Turkey) based on a sensitivity approach

Solak KC, Tuncay E, Ulusay R.

Bulletin of engineering geology and the environment

2017; 76(4):1321-1341

ARTICLE IDENTIFIERS

DOI: 10.1007/s10064-017-1025-4

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 1435-9529

eISSN: 1435-9537

OCLC ID: 635690809

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.