

Pinched cord and overdriven staple failures: research on the causation of an electrical fire

Novak C, Keller M, Meza T, McKinnies J, Espinosa E, Calhoun K.

Fire technology

2018; 54(4):921-941

ARTICLE IDENTIFIERS

DOI: 10.1007/s10694-018-0715-1

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: 65009890

pISSN: 0015-2684

eISSN: 1572-8099

OCLC ID: 1569307

CONS ID: FITCAA

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.