

Flame characteristics and heat flux profile of a tank surface caused by horizontal gas leak jet fire impingement

Tang F, Peng X, Palacios A.

Fire safety journal

2022; 134:e103709

ARTICLE IDENTIFIERS

DOI: 10.1016/j.firesaf.2022.103709

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available

pISSN: 0379-7112

eISSN: not available

OCLC ID: not available

CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.