

Fire Fighter Dies after Being Ejected from a Pumper in a Single Vehicle Rollover Crash: The NIOSH Report

Miles S.

Accident reconstruction journal

2009; 19(5):19-22

ARTICLE IDENTIFIERS

DOI: unavailable

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: 96640898

pISSN: 1057-8153

eISSN: not available

OCLC ID: 20782681

CONS ID: sn 91002145

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.