

A theoretical examination of the possibility of spontaneous combustion of laundry in tumble dryers

Jones JC.

Journal of fire sciences

2001; 19(3):181-189

ARTICLE IDENTIFIERS

DOI: 10.1106/FPUV-B2HN-YNC2-TWE5

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: 83643900

pISSN: 0734-9041

eISSN: 1530-8049

OCLC ID: 08822978

CONS ID: sn 82006978

US National Library of Medicine ID: 9890136

This article was identified from a query of the SafetyLit database.