

NCHRP Report 350 compliance testing of the beam-eating steel terminal system

Pfeifer B, Sicking D.

Transportation research record

1998; 1647:130-138

ARTICLE IDENTIFIERS

DOI: 10.3141/1647-16

PMID: unavailable

PMCID: not available

JOURNAL IDENTIFIERS

LCCN: 74032372

pISSN: 0361-1981

eISSN: 2169-4052

OCLC ID: 01259379

CONS ID: not available

US National Library of Medicine ID: 101481512

This article was identified from a query of the SafetyLit database.