

## **Effects of inadequate driveway corner clearances on traffic operations, safety, and capacity**

Gan CT, Long G.

Transportation research record

1997; 1579:35-42

### **ARTICLE IDENTIFIERS**

DOI: 10.3141/1579-05

PMID: unavailable

PMCID: not available

### **JOURNAL IDENTIFIERS**

LCCN: 74032372

pISSN: 0361-1981

eISSN: 2169-4052

OCLC ID: 01259379

CONS ID: not available

US National Library of Medicine ID: 101481512

This article was identified from a query of the SafetyLit database.