Field survey of slope failures occurred in Fukui prefecture due to heavy rainfall in July 2018 -Aerial photograph by using UAV and slope stability analysis-

Tsujino K, Kobayashi T. Journal of Japan Society for Natural Disaster Science 2020; 39(1):23-34

ARTICLE IDENTIFIERS

DOI: 10.24762/jndsj.39.1_23

PMID: unavailable PMCID: not available

JOURNAL IDENTIFIERS

LCCN: not available pISSN: 0286-6021 eISSN: 2434-1037 OCLC ID: not available CONS ID: not available

US National Library of Medicine ID: not available

This article was identified from a query of the SafetyLit database.